


























EXTENSIVE DISTORTION ALONG LOWER CHORD
DUE TO ICE DAMAGE









HEAVY SECTION LOSS ALONG STRINGER 2 IN
FLOORBEAM BAY 4



60%-70% SECTION LOSS ALONG BOTTOM FLANGE
OF STRINGER 2 IN FLOORBEAM BAY 4







9-00
STR. 2
F.B. & WEST

9-02-01
ST 3
B. 2
(M)

STR 3
F.B. 1





FBI

UPSTREAM FIXED PED. BEARING AT ABUT. 1 HAS
ROTATED BACKWARDS PULLING UP FROM THE
BRIDGE SEAT DUE TO PAST SUB. MOVEMENT



