


























Mark 5 10070
1999
UT Inspector

JEFF
CLANK






















































S.W.



























CORROSION DUE TO LEAKING WEEP TUBE











