









LACK OF APPR. RAIL ALONG WITH BLUNT TERMINUS
IS A TRAFFIC SAFETY HAZARD

















































DECK HAS HIGH POTENTIAL FOR RANDOM FULL DEPTH
FAILURES















50% OF BEARING #6 IS UNDERMINED DUE TO SEVERE SPALLING ALONG ABUT. #2 BRIDGE SEAT







