





University of Vermont
Champlain College
Trinity College
EXIT 16 N



Large hole in side of invert.



Cracks and small holes and possible crushing.





Trees and grass and debris need to be removed
from right of way fence.



Culvert needs to be flushed.



Colvert will need replacing in the near future.

