

A photograph of a concrete wall. A vertical crack runs down the center of the image. A horizontal stain, possibly from water or paint, is visible across the middle. The wall has a rough, textured appearance with some discoloration.

06.18.2007 11:26