



05.04.2007 09:49





05.04.2007 09:49





05.04.2007 09:51





05.04.2007 09:51





05.04.2007 09:53





05.04.2007 09:54





05.04.2007 09:55





05.04.2007 09:55





05.04.2007 09:55



A close-up photograph of a dark gray asphalt surface. The surface is heavily textured with small stones and is marked by several prominent, irregular cracks. A large, jagged crack runs vertically through the center-left of the frame. Another crack runs horizontally across the middle, and a third crack runs vertically on the right side. The bottom of the image shows a lighter, more sandy or gravelly area, possibly a repair or a different layer of the pavement.

05.04.2007 09:56





05.04.2007 09:56





05.04.2007 09:56





05.04.2007 09:59





05.04.2007 10:01





05.04.2007 10:01





05.04.2007 10:02





05.04.2007 10:03





05.04.2007 10:04





05.04.2007 10:04





05.04.2007 10:05





05.04.2007 10:06





05.04.2007 10:06