

A photograph of a two-lane asphalt road with a metal guardrail on the right side. The road surface is heavily cracked, with a prominent longitudinal crack on the left and a diagonal crack on the right. Yellow double lines mark the center of the road. Green vegetation is visible along the edges of the road. A date stamp is located in the bottom right corner.

08/07/2020