



05.08.2006 11:05





05.08.2006 11:05









05.08.2006 11:06





05.08.2006 11:08





05.08.2006 11:08



A close-up photograph of a dark gray asphalt surface. A prominent vertical crack runs down the center of the frame. To the left of this crack, there is a large, irregular area of surface distress characterized by numerous small, interconnected cracks, suggesting a pothole or a severely deteriorated section of the pavement. The overall texture of the asphalt is granular and uneven.

05.08.2006 11:09





05.08.2006 11:09





05.08.2006 11:09





05.08.2006 11:10





05.08.2006 11:10









05.08.2006 11:10





05.08.2006 11:11





05.08.2006 11:11





05.08.2006 11:11





05.08.2006 11:12





05.08.2006 11:12





05.08.2006 11:12





05.08.2006 11:13





05.08.2006 11:13





05.08.2006 11:14





05.08.2006 11:14





05.08.2006 11:14





05.08.2006 11:15





05.08.2006 11:15





05.08.2006 11:16





05.08.2006 11:17