





Scattered preforations throughout invert.




















U/M 15016
HT 1000000

REPAIR TO CORROSION
50A 3025









