

Trees and debris needs to be removed from
inlet end of pipe.

