

A close-up photograph of a metal surface, likely a roof or industrial structure, featuring a horizontal seam. The metal is heavily corroded, with a mottled, brownish-grey patina. A horizontal line of bolts runs across the middle of the image, securing a seam. The bolts are hexagonal and show signs of rust. The text "BOLTLINE CRACKING" is overlaid in blue, bold, sans-serif font, centered horizontally and positioned slightly above the bolt line. The lighting is somewhat uneven, highlighting the texture of the corrosion and the metallic sheen of the bolts.

BOLTLINE CRACKING