




HEAVY RUST AND CORROSION WITH SCATTERED
PREFORATIONS AT THE OUTLET.