







Outlet end of culvert should be repaired
and a collar installed. Outlet has pulled
apart and dropped about 1 foot.



















Trees in channel at outlet need to be

