









Heavy corrosion throughout pipe.





Credde headwall at inlet should be anchored
and erosion repaired.











