


















areas of extensive corrosion and scattered perforations











Stone heatwall at inlet should be repaired











Bank erosion at outlet should be repaired.