

















A photograph showing a concrete cradle headwall. The wall is made of several vertical panels and shows signs of aging, including numerous fine cracks and large, vertical orange stains that appear to be rust or mineral deposits. To the left of the concrete wall is a curved, corrugated metal structure, possibly a culvert or part of a bridge. The top of the wall is bordered by a chain-link fence and overgrown vegetation, including green grass and some yellowing leaves. At the base of the wall, there is a dark, narrow channel or ditch containing some fallen leaves and small green plants. The overall scene suggests an outdoor, possibly rural or semi-rural, environment.

Minor map cracking in craddle headwall.



















The image shows a close-up of a metal structure, likely a ship's hull or a large industrial tank. It features several vertical metal strips or plates held together by bolts. The surface is heavily corroded, with large areas of bright orange-red rust visible, particularly along the joints and in the lower half of the frame. The upper half shows more of the original metal color, which appears to be a mix of grey and light brown. The text "Preforations at outlet." is overlaid in blue in the center.

Preforations at outlet.







