







09/04/2020





09/04/2020





09/04/2020





09/04/2020





09/04/2020





09/04/2020





09/04/2020





09/04/2020





09/04/2020













09/04/2020









09/04/2020

















09/04/2020



A photograph showing the underside of a concrete ceiling. A prominent vertical crack runs down the center. Two horizontal concrete beams are visible, one on the left and one on the right, meeting the ceiling. The concrete surface is weathered and shows some staining. A date stamp is located in the bottom right corner.

09/04/2020





09/04/2020













09/04/2020





09/04/2020









09/04/2020









09/04/2020





09/04/2020



A photograph showing a corner of a building. The left wall is painted a dark green/blue color, which is heavily peeling and chipped away in several places, revealing a lighter, possibly white or grey, surface underneath. Two small, oval-shaped holes or indentations are visible on this wall. The right wall is a light grey or off-white color, also showing signs of wear and peeling. A vertical wooden plank or piece of trim is positioned in the corner where the two walls meet. At the base of the walls, there is a concrete or stone ledge. On top of this ledge, there is a pile of debris, including what looks like dried leaves, twigs, and some small pieces of wood or metal. The overall appearance is one of neglect and decay.

09/04/2020



A photograph showing a close-up of a concrete structure, possibly a bridge or a large wall. The concrete is light gray and shows signs of weathering and cracking. A horizontal concrete beam is visible in the upper part of the image. Below it, there is a gap or opening. In the bottom right corner, there is a date stamp in orange text that reads "09/04/2020". The background shows some green foliage, suggesting an outdoor setting.

09/04/2020





09/04/2020





09/04/2020









09/04/2020








A photograph of a concrete wall, likely in a basement or crawlspace. A large, vertical crack runs down the center of the wall. To the left of the crack, the concrete is light-colored and textured. To the right, the wall is covered in dark, vertical streaks and stains, possibly from water or moisture. The top of the wall shows some structural elements, including a horizontal beam and a corner. The bottom of the image shows a dark, reflective surface, possibly water or a wet floor.

09/04/2020



A photograph of a geological rock sample. The rock is light-colored, possibly tan or beige, with a rough, textured surface. A prominent vertical crack runs down the center of the sample. To the right of the crack, there is a dark, irregularly shaped area that appears to be a void or a different mineral phase. The bottom of the image is dark and blurry. A date stamp in orange text is located in the bottom right corner.

09/04/2020



A photograph showing a close-up view of a concrete bridge structure. The image captures a large, weathered concrete beam with visible cracks and discoloration. Several metal bolts or fasteners are visible, securing the beam. In the background, green foliage and trees are visible through the bridge's opening. A date stamp is present in the lower right corner.

09/04/2020









09/04/2020









09/04/2020













09/04/2020





09/04/2020





09/04/2020









09/04/2020



























