

A photograph of a concrete wall. On the left, there is a rough, textured concrete surface. To the right, a smoother concrete surface is visible, but it is heavily stained with dark, vertical streaks that appear to be water or oil. A prominent vertical crack runs down the center of the smoother section. Above the main wall, a horizontal concrete beam or ledge is visible, showing some peeling paint or surface degradation. The overall lighting is somewhat dim, and the colors are muted, with greys, browns, and blacks dominating the scene.

09/04/2020