

A photograph of a road surface showing a significant longitudinal crack. The road is paved with asphalt and has double yellow lines. A concrete curb is visible on the right side. A date stamp is present in the bottom right corner.

07/15/2020