Heavy rot and crushing along bent
Missing piles below bearing area