

UPSTREAM FIXED PED. BEARING AT ABUT. 1 HAS
ROTATED BACKWARDS PULLING UP FROM THE
BRIDGE SEAT DUE TO PAST SUB. MOVEMENT

