













* Note missing connection bolts which are pulling out of ferrules.

Abutment #2 (north) southbound lane













































