

Craddle headwall at outlet should be plumbed
and anchored.

