





culvert should be flushed.

















Extensive corrosion and scattered perforations throughout.

















