

Heavy corrosion throughout pipe.

