

113



Bank erosion needs to be repaired.



















Wingwall east side of
repair or replacement







Minor bank repair at outlet.

