

Craddle headwall at outlet should be anchored.

































