















Culvert needs to be flushed



More then half full at outlet.









