

A photograph taken from underneath a bridge, looking up at the structural components. A large, dark, irregular hole is visible in a horizontal steel beam. To the right, a concrete slab also shows a smaller, circular hole. The steel beam has a greenish-grey patina and several red, rust-like patches. A diagonal steel truss member is visible on the right side of the frame. The background is a bright, overexposed sky. The date '07/30/2020' is printed in orange at the bottom center.

07/30/2020