

STATION		POS.	203.15	203.16	203.30	301.28	402.12 (MOD.)	NEW PIPE			604.40	604.412	616.35	620.30	616.47	501.25	507.15	621.20	621.20	621.505	621.60	621.52	621.80	REMARKS	
BEGIN	END		COMMON EXCAV. m³	SOLID ROCK EXCAV. m³	EARTH BORROW m³	SUBBASE OF CR. GRAVEL T	AGGREGATE SHOULDERS T	D	L	TH/CL	GRATE TYPE EA	CHAN ELEV EA	REHAB DI CLASS I EA	TREATED TIMBER CURB M	DRIVE GATE FOR WW/FENCE EA	BIT. CONC. GUTTERS & TRAFFIC ISLANDS T	CONC. CLASS B m³	REINF. STEEL KG	STEEL BEAM G.R. M	STEEL BEAM G.R. (MOD) M	MANUFACT. TERMINAL SECTION EA	ANCHOR FOR STEEL BEAM RAIL EA	TRAILING END TERMINAL EA	REMOVAL AND DISPOSAL OF G.R. M	
2+323	2+324	NEED.											II			0.50								57	REHAB DI AND DISPOSAL OF EXISTING GUARDRAIL
2+324	2+325	NEED.			20								II			0.75				I	I	I			REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+325	2+326	NEED.											II						42					215	REHAB DI AND DISPOSAL OF EXISTING GUARDRAIL
2+326	2+327	NEED.											II			3.50					I			54	REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+327	2+328	NEED.			20			450	15	CPEP(SL)	I-B		2				2.23	103	202				I		REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+328	2+329	NEED.											II			0.75					I				REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+329	2+330	NEED.											II	654		0.75			39						REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+330	2+331	NEED.											II			0.75								235	REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+331	2+332	NEED.											I						231						REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+332	2+333	NEED.			20								I								I	I		313	REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+333	2+334	NEED.			20								I			0.75					I			107	REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+334	2+335	NEED.											I			0.25					I	I			REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+335	2+336	NEED.											I			26			308				I		REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+336	2+337	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+337	2+338	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+338	2+339	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+339	2+340	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+340	2+341	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+341	2+342	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+342	2+343	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+343	2+344	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+344	2+345	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+345	2+346	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+346	2+347	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+347	2+348	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+348	2+349	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+349	2+350	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+350	2+351	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+351	2+352	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+352	2+353	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+353	2+354	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+354	2+355	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+355	2+356	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+356	2+357	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+357	2+358	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+358	2+359	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+359	2+360	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+360	2+361	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+361	2+362	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+362	2+363	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+363	2+364	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+364	2+365	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+365	2+366	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+366	2+367	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+367	2+368	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+368	2+369	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+369	2+370	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+370	2+371	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+371	2+372	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+372	2+373	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+373	2+374	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+374	2+375	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+375	2+376	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+376	2+377	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+377	2+378	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+378	2+379	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+379	2+380	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+380	2+381	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+381	2+382	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+382	2+383	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+383	2+384	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+384	2+385	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+385	2+386	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+386	2+387	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+387	2+388	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+388	2+389	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+389	2+390	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+390	2+391	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+391	2+392	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+392	2+393	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+393	2+394	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+394	2+395	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+395	2+396	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+396	2+397	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+397	2+398	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+398	2+399	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+399	2+400	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+400	2+401	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+401	2+402	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+402	2+403	NEED.											I												REHAB DI NEW CONSTRUCT NEW BITUMINOUS CONCRETE GUTTER
2+403	2+404	NEED.																							