

Filled out by: G J Demers

Date: 02 / 03 / 2010

Crossing Inspection Form

Railroad: WACR CRL B/S	Town: NEWBURY
Valuation Sheet: V 43 / 33	Valuation Stationing: 1732 + 58
Mile Post: D 8.17	GPS Coordinates: N: 44 03.018 W: 72 04.896

Crossing Name: _____

Type: ☐ Public ☐ Private ☒ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 053 -

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 115 RE Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







