

Filled out by: G J Demers

Date: 02 / 01 / 2010

Crossing Inspection Form

Railroad: WACR CRL B/S	Town: NEWBURY
Valuation Sheet: V 43 /	Valuation Stationing: 1795 + 65
Mile Post: D 6.98	GPS Coordinates: N: 44 03.868 W: 72 03.591

Crossing Name: LARRY SCOTT

Type: ☐ Public ☐ Private ☒ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number ~~053~~

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☒ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☒ Rubber ☐ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 115 RE Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____