

Filled out by: G J Demers

Date: 06 / 27 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRR</u>
Valuation Sheet: Page <u>11</u> of <u>18</u>	Valuation Stationing: <u>403 + 15</u>
Mile Post: M <u>7.63</u>	GPS Coordinates: N: <u>44 11 58</u> W: <u>72 30 22</u>

Crossing Name: GRANITE STREET

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 037-348F

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 80 Rail Condition ☐ Good ☒ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____









Filled out by: G J Demers

Date: 06/27/2014

Crossing Inspection Form

Railroad: MBL	Town: BARE
Valuation Sheet: 11 of 18	Valuation Stationing: 403 + 15
Mile Post: M 7.63	GPS Coordinates: N: 44 11.58 W: 72 30.22

Crossing Name: GRANITE STREET (SIDING)

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☐ Main Track ☒ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 037 - 340F

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 90 Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







