



Filled out by: G J Demers

Date: 06/27/2014

Crossing Inspection Form

Railroad: MBL	Town: BARRE
Valuation Sheet: 11 of 18	Valuation Stationing: 417 + 90
Mile Post: M 7.91	GPS Coordinates: N: 44 11.48 W: 72 30.08

Crossing Name: PROSPECT STREET

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 837-352V

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 80 Rail Condition ☐ Good ☒ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____









