

Filled out by: G J Demers

Date: 05 / 22 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRE</u>
Valuation Sheet: Page <u>17</u> of <u>18</u>	Valuation Stationing: <u>666 + 64</u>
Mile Post: M <u>12.63</u>	GPS Coordinates: N: <u>44 09 08</u> W: <u>72 29 10</u>

Crossing Name: Mc LEOD HILL

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 837 - 368 S

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☐ Fair ☒ Poor

Rail Size / Type 05 Rail Condition ☐ Good ☐ Fair ☒ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____



DANGER
ADMITTANCE
LIMITED TO
AUTHORIZED PERSONNEL



NO TRUCKS
OVER 10,000 LBS





