

Filled out by: G J Demers

Date: 03 / 16 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: COVENTRY
Valuation Sheet: V 43 / 98	Valuation Stationing: 5151 + 53
Mile Post: L 6.62	GPS Coordinates: N: 44 50.549 W: 72 12.403

Crossing Name: HOWSE ROAD

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - B72K

Signalled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____



WACR
850-872K
U.S. DOT-AAR







