

Filled out by: G J Demers

Date: 03 / 16 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: IRASBURG
Valuation Sheet: V 43 / 98	Valuation Stationing: 5131 + 79
Mile Post: L 6.99	GPS Coordinates: N: 44 50.222 W: 72 12.371

Crossing Name: _____

Type: ☐ Public ☐ Private ☒ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - 874Y

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 1

Remedial Action (if any) _____

250874Y

CROSS LABORATORY







