

Filled out by: G J Demers

Date: 03 / 16 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: IRASBURG
Valuation Sheet: V 43 / 97	Valuation Stationing: 5096 + 80
Mile Post: L 8.03	GPS Coordinates: N: 44 49.364 W: 72 12.203

Crossing Name: LA MONDA

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☐ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - 877 U

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____



WACR
850-877U
U.S. DOT-AAR









