

Filled out by: G J Demers

Date: 01 / 18 / 2010

### Crossing Inspection Form

|                                      |                                                  |
|--------------------------------------|--------------------------------------------------|
| Railroad: <b>WACR CRL L/S</b>        | Town: <b>BURKE</b>                               |
| Valuation Sheet:<br><b>V 43 / 77</b> | Valuation Stationing:<br><b>4042 + 07</b>        |
| Mile Post:<br><b>L 27.63</b>         | GPS Coordinates:<br>N: 44 37.850<br>W: 71 58.375 |

Crossing Name: US 5

Type: ☒ Public ☐ Private ☐ Farm ☐ Other \_\_\_\_\_

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other \_\_\_\_\_

AAR DOT Number 850 - 913 M

Signaled ☒ Yes ☐ No      Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other \_\_\_\_\_

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 100 REHF      Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_



CROSSROAD

WACR  
850-913M  
U.S. DOT-AAR

















