

Filled out by: G J Demers

Date: 01 / 18 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BURKE
Valuation Sheet: V 43 / 77	Valuation Stationing: 40 30 + 50
Mile Post: L 27.85	GPS Coordinates: N: 44 37.716 W: 71 58.194

Crossing Name: HAYDEN CROSSING

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - 914 U

Signaled ☒ Yes ☐ No Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☐ Fair ☒ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____



WACR
850-914U
U.S. DOT-AAR

MADE IN CANADA



A vertical wooden utility pole stands in the center of the frame, surrounded by dense green foliage. Two white identification tags are attached to the pole. The top tag displays the number '27.85' in black. The bottom tag displays the alphanumeric code '850 914 U' in black. A yellow measuring tape is visible, wrapped around the pole behind the tags. The background is filled with the branches and leaves of trees, with a bright sky visible through the canopy.

27.85

850 914 U









