

Filled out by: G J Demers

Date: 01 / 15 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: St. JOHNSBURY
Valuation Sheet: V 43 /	Valuation Stationing: 3255 + 75
Mile Post: L 42.54	GPS Coordinates: N: 44 25.823 W: 72 01.079

Crossing Name: US 5

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - 935 M

Signaled ☒ Yes ☐ No Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Wheel cut ☐ Other _____

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____

RAILROAD
CROSSING

WACR
850-935M
U.S. DOT-AAR

MADE IN CANADA













