

Filled out by: G J Demers

Date: 01 / 15 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: St. JOHNSBURY
Valuation Sheet: V 43 / 62	Valuation Stationing: 3244 + 52
Mile Post: L 42.74	GPS Coordinates: N: 44 25 . 40 W: 72 00 . 57

Crossing Name: TIMSON

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 850 - 937B

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____



4

7

8

850 937

8

80



RAILROAD STREET
APARTMENTS
18 - 19 - 20



WARNING
PRIVATE CROSSING
USE BY PUBLIC PROHIBITED
EXCEPT ON EMERGENCY VEHICLES
SEE SIG AT 100 YD AHEAD

Certainfeed



