

Filled out by: **G J Demers**

Date / Time: 10/03/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>RUTLAND</u>
Valuation Sheet: V 3 / 52	Valuation Stationing: <u>2725+12</u>
Mile Post: B 51.61	GPS Coordinates: N: <u>43.59610</u> W: <u>72.96903</u>

Crossing Name: ALLAN STREET

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 851 285 M

Signaled ☒ Yes ☐ No Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 105 Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







