

Filled out by: G J Demers

Date: 01 / 03 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: RYEGATE
Valuation Sheet: V 43 / 45	Valuation Stationing: 2345 + 02
Mile Post: L 59.77	GPS Coordinates: N: 44 12.313 W: 72 03.630

Crossing Name: PAPER MILL ROAD

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 857 - 612 R

Signaled ☒ Yes ☐ No Crossbucks ☐ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel ☐ Planks

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 100 REHF Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____

857 612 R

3





RAILROAD
CROSSING

857-612R

2

TRACKS







RAILROAD
CROSSING

857-612R

2
TRACKS

X