

UPDATE

Filled out by: G J Demers

Date / Time: 05/28/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>ROCKINGHAM</u>
Valuation Sheet: V 3 / 8	Valuation Stationing: <u>377 + 47</u>
Mile Post: B 7.15	GPS Coordinates: N: <u>43.20849</u> W: <u>72.51115</u>

Crossing Name: SEVERANCE

Type: ☐ Public ☒ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number _____

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 90 DY Rail Condition ☐ Good ☒ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







