

Filled out by: G J Demers

Date / Time: 06/05/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 13	Valuation Stationing: <u>660 + 18</u>
Mile Post: B 12.50	GPS Coordinates: N: <u>45.25615</u> W: <u>72.57705</u>

Crossing Name: SEWAGE PLANT

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number 859 810T

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☒ Paved ☐ Concrete ☐ Rubber Panels ☐ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☒ Good ☐ Fair ☐ Poor

Rail Size / Type 105 DY Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







