

Filled out by: G J Demers

Date / Time: 06/12/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 16	Valuation Stationing: <u>809+08</u>
Mile Post: B <u>15.32</u>	GPS Coordinates: N: <u>43.28944</u> W: <u>72.60717</u>

Crossing Name: COLBURN

Type: ☐ Public ☒ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number —

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 90 DY Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







