

Filled out by: **G J Demers**

Date / Time: 06/18/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 18	Valuation Stationing: <u>946 + 85</u>
Mile Post: B <u>17.94</u>	GPS Coordinates: N: <u>43.32607</u> W: <u>72.61114</u>

Crossing Name: GASSETT'S

Type: ☐ Public ☒ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number _____

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No STOP SIGNS

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 105 DY Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 6

Remedial Action (if any) _____



STOP
PROCEED
SLOWLY





