

Filled out by: **G J Demers**

Date / Time: 06/19/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 19	Valuation Stationing: <u>985 + 81</u>
Mile Post: B <u>18.65</u>	GPS Coordinates: N: <u>43.33516</u> W: <u>72.61429</u>

Crossing Name: THOMAS'

Type: ☐ Public ☒ Private ☐ Farm ☐ Other _____

Location: ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number _____

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel BOLCAST

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☐ Good ☐ Fair ☒ Poor

Rail Size / Type 105 DY Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







