

Filled out by: **G J Demers**

Date / Time: 07/11/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V 3 / 26	Valuation Stationing: <u>1339+18</u>
Mile Post: B 25.36	GPS Coordinates: N: <u>43.38580</u> W: <u>72.66636</u>

Crossing Name: INDUSTRIAL

Type: ☐ Public ☒ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number _____

Signaled ☐ Yes ☒ No Crossbucks ☐ Yes ☒ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel

Flangeway ☐ Rubber ☐ Rail ☐ Plank ☒ Other WHEEL CUT

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type 105 Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____







